CATÁLOGO DE PRODUTOS **RSE**

PRODUTO: RELÉ RS41F





RELÉ RS41F

c **Al** us

File No.: E133481



File No.: 40020043



File No.: CQC17002175724



Features

- Slim size (width 5mm)
- 6A switching capability 4kV dielectric strength (between coil and contacts)
- Surge voltage up to 6kV (between coil and contacts)
- Meeting VDE 0700, 0631 reinforce insulation
- High sensitive: Approx.170mW
- Sockets available
- 1 Form A and 1 Form C configurations

CONTACT DATA

CONTACT DATA			
Contact arrangement	1A, 1C		
Contact resistance ¹⁾	100mΩ max. (at 1A 6VDC) Gold plated: 30mΩ max.(at 1A 6VDC)		
Contact material	AgSnO ₂ , AgNi		
Contact rating (Res. load)	6A 250VAC / 30VDC		
Max. switching voltage	400VAC / 125VDC		
Max. switching current	6A		
Max. switching power	1500VA / 180W		
Mechanical endurance	1 x 10 ⁷ ops		
Electrical endurance	H type: 6 x 10 ⁴ oPs (6A 250VAC/30VDC, Resistive load, AgNi, at 85°C, 1s on 9s off) Z type: 3 x 10 ⁴ oPs (NO, 6A 250VAC/30VDC, Resistive load, AgNi, at 85°C, 1s on 9s off) 1 x 10 ⁴ oPs (NC, 6A 250VAC/30VDC, Resistive load, AgNi, at 85°C, 1s on 9s off)		

Notes:1) The data shown above are initial values.

CHARACTERISTICS

Insulation	resistance		1000MΩ (at 500VDC)
Dielectric	Between o	coil & contacts	4000VAC 1 min
strength	Between o	open contacts	1000VAC 1 min
Operate tir	me (at nom	i.volt.)	8ms max.
Release ti	me (at nom	i.volt.)	4ms max.
Shock resistance*1)	Functional	49m/s²	
SHOCK TEST	istalice**	Destructive	980m/s²
Vibration r	esistance*	1)	10Hz to 55Hz 1mm DA
Humidity		5% to 85% RH	
Ambient te	emperature		-40°C to 85°C
Termination		PCB	
Unit weigh	nt		Approx. 5g
Construction		Plastic sealed, Flux proofed	

Notes: 1) Index is that of relay without socket and is not in relay length direction.

- 2) The data shown above are initial values.
- 3) Please find coil temperature curve in the characteristic curves below.
- Please do not install a SPDT(1 Form C) type relay on either of the smallest sides or facing downward.
- 5) UL insulation system: Class A.

COIL

Coil power 5VDC to 24VDC: Approx. 170mW 48VDC, 60VDC: Approx. 210mW

COIL DATA

at 23°C

at 2				
Nominal Voltage VDC	Pick-up Voltage VDC max. ¹⁾	Drop-out Voltage VDC min. ¹⁾	Max. Voltage VDC ³⁾	Coil Resistance Ω
5	3.75	0.25	7.5	147 x (1±10%)
6	4.50	0.30	9.0	212 x (1±10%)
9	6.75	0.45	13.5	476 x (1±10%)
12	9.00	0.60	18	848 x (1±10%)
18	13.5	0.90	27	1906 x (1±15%)
24	18.0	1.20	36	3390 x (1±15%)
48 ⁴⁾	36.0	2.40	72	10600 x (1±15%)
60 ⁴⁾	45.0	3.00	90	16600 x (1±15%)

Notes: 1) The data shown above are initial values.


- 2) When require pick-up voltage ≤70% nominal voltage, special order allowed .
- Maximum voltage refers to the maximum voltage which relay coil could endure in a short period of time.
- 4) For products with rated voltage ≥ 48V, measures should be taken to prevent coil overvoltage in order to protect coil in test and application (eg. Connect diodes in parallel).

SAFETY APPROVAL RATINGS

OAI ETT AFFROVAL KATINGO				
	6A 30VDC at 85°C			
UL/CUL	6A 277VAC at 85°C			
	R300			
	B300			
VDE	6A 30VDC at 85°C			
	6A 250VAC at 85°C			

Notes: 1) All values unspecified are at room temperature.

 Only typical loads are listed above. Other load specifications can be available upon request.




- 2) We recommend flux proofed types for a clean environment (free from contaminations like H₂S, SO₂, NO₂, dust, etc.). We suggest to choose plastic sealed types and validate it in real application for an unclean environment (with contaminations like H₂S, SO₂, NO₂, dust, etc.).
- 3) Contact is recommended for suitable condition and specifications if water cleaning or surface process is involved in assembling relays on PCB.

4) For gold plated type, the min. switching current and min. switching voltage is 10mA 5VDC.

5) The customer special requirement express as special code after evaluating by Hongfa. e.g. (210) stands for pick-up voltage less than 70% of norminal voltage. e.g. (414) stands for wide coil pin type.

6) Standard tube packing length is 550mm. Any special requirement needed, please contact us for more details.


7) For products that should meet the explosion-proof requirements of "IEC 60079 series", please note [Ex] after the specification while




Outline Dimensions

1 Form A

Special code: (414)



1 Form C





PCB Layout (Bottom view)

1 Form A


1 Form C


Vertical version







Flat pack version







Special code: (414)






Wiring Diagram (Bottom view)






- Remark: 1) In case of no tolerance shown in outline dimension: outline dimension ≤1mm, tolerance should be ±0.2mm; outline dimension >1mm and ≤5mm, tolerance should be ±0.3mm; outline dimension >5mm, tolerance should be ±0.4mm.
 - 2) The tolerance without indicating for PCB layouts is always ±0.1mm.


MAXIMUM SWITCHING POWER



ENDURANCE CURVE



COIL TEMPERATURE RISE




Percentage Of Nominal Coil Voltage

Test conditions:

6A 85℃

(Typical curve of 24VDC standard type)

LOAD SWITCHING CAPACITY CURVE




Test conditions: NO, Room temp.


Test conditions:

NO, AgNi, Resistive load, 250VAC, Flux proofed, Room temp., 1s on 9s off.

BREAKING CAPACITY TRIP CURVE AC INDUCTIVE LOAD ENDURANCE CURVE




Test conditions: Room temp., Plastic sealed, 1s on 9s off.



Test conditions:

NO, AgNi, Plastic sealed, Room temp.,
250VAC

DC INDUCTIVE LOAD ENDURANCE CURVE



Test conditions:

NO, AgNi,Plastic sealed, Room temp., 24VDC

Notes: Characteristic data is not guaranteed value but measured values of samples from production line.

Relay Sockets



Features

- The dielectric strength can reach 4000VAC and the insulation resistance is 1000MΩ
- With finger protection device
- Ensure secure rention and easy ejection of relays
- Built-in protection circuit can indicate the power status, protect the circuit and expand the range of relay input voltage
- Components available: marker, jumper and separator
- Environmental friendly product (RoHS compliant)


CHARACTERISTICS

Туре	Nominal Voltage	Nominal Current	Ambient Temperature	Input Voltage	Relay's Applicable Rated Voltage	Polarity of Input Voltage	Wire Strip Length	Screw Torque	Unit weight
41F-1Z-C2-1	250VAC	6A	-40 °C to 70 °C	(12 to 24)VAC/DC	(12 to 24)VDC	No requirement	7mm	0.5N · m	Approx.27g
41F-1Z-C2-2	250VAC	6A	-40 $^{\circ}\text{C}~$ to 70 $^{\circ}\text{C}$	(48 to 60)VAC/DC	(48 to 60)VDC	No requirement	7mm	0.5N · m	Approx.25g
41F-1Z-C2-3	250VAC	6A	-40 °C to 55 °C	(110 to 125)VAC/DC	60V DC	No requirement	7mm	0.5N · m	Approx.27g
41F-1Z-C2-4	250VAC	6A	-40 °C to 55 °C	(220 to 240)VAC/DC	60V DC	No requirement	7mm	0.5N · m	Approx.27g
41F-1Z-C2-5	250VAC	6A	-40 $^{\circ}\text{C}~$ to 70 $^{\circ}\text{C}$	(6 to 24)VDC	(6 to 24)VDC	Requirement	7mm	0.5N · m	Approx.24g
41F-1Z-C2-5(012)	250VAC	6A	-40 °C to 70 °C	(6 to 24)VDC	(6 to 24)VDC	No requirement	7mm	0.5N · m	Approx.24g
41F-1Z-C4-1	250VAC	6A	-40 $^{\circ}\text{C}~$ to 70 $^{\circ}\text{C}~$	(12 to 24)VAC/DC	(12 to 24)VDC	No requirement	7mm		Approx.25g
41F-1Z-C4-2	250VAC	6A	–40 $^{\circ}\text{C}~$ to 70 $^{\circ}\text{C}$	(48 to 60)VAC/DC	(48 to 60)VDC	No requirement	7mm		Approx.24g
41F-1Z-C4-3	250VAC	6A	-40 °C to 55 °C	(110 to 125)VAC/DC	60VDC	No requirement	7mm		Approx.25g
41F-1Z-C4-4	250VAC	6A	-40 °C to 55 °C	(220 to 240)VAC/DC	60VDC	No requirement	7mm		Approx.25g
41F-1Z-C4-5	250VAC	6A	-40 $^{\circ}\text{C}~$ to 70 $^{\circ}\text{C}~$	(6 to 24)VDC	(6 to 24)VDC	Requirement	7mm		Approx.23g
41F-1Z-C10-1	250VAC	6A	-40 °C to 70 °C	(12 to 24)VAC/DC	(12 to 24)VDC	No requirement	10mm		Approx.22.5g
41F-1Z-C10-2	250VAC	6A	-40 °C to 70°C	(48 to 60)VAC/DC	(48 to 60)VDC	No requirement	10mm		Approx.22.5g
41F-1Z-C10-3	250VAC	6A	-40 °C to 55 °C	(110 to 125)VAC/DC	60VDC	No requirement	10mm		Approx.23.1g
41F-1Z-C10-4	250VAC	6A	-40 °C to 55 °C	(220 to 240)VAC/DC	60VDC	No requirement	10mm		Approx.23.1g
41F-1Z-C10-5	250VAC	6A	-40 °C to 70 °C	(6 to 24)VDC	(6 to 24)VDC	Requirement	10mm		Approx.22.4g
41F-1Z-A1	250VAC	6A	-40 °C to 70 °C	(6 to 60)VDC	(6 to 60)VDC	Requirement			Approx.2.9g
41F-1Z-A2-1	250VAC	6A	-40 °C to 70 °C	(6 to 24)V DC	(6 to 24)V DC	Requirement			Approx.4g
41F-1Z-A2-2	250VAC	6A	-40 °C to 70°C	(48 to 60)V DC	(48 to 60)V DC	Requirement			Approx.4g

Note: When the 41F-1Z-C2/C4-1 socket is applied to the relay of 12VDC nominal voltage, the relay of which pick-up voltage =70% nominal voltage should be required and the special order of relay allowed. 41F-1Z-C2/C4-4 is not allowed in continuous electricity conditions.

OUTLINE DIMENSIONS, WIRING DIAGRAM AND PC BOARD LAYOUT

Unit: mm



OUTLINE DIMENSIONS, WIRING DIAGRAM AND PC BOARD LAYOUT

Unit: mm


Socket	Outline Dimensions	Wiring Diagram	Components Available
41F-1Z-C10-1/2/3/4/5	97.6	COIL AND AND INDICATION CIRCUIT TIE NO TECTION TIE	marker 41F-M 41F-M1 jumper 41F-J1(blue) 41F-J1R(red) 41F-J1B(black) separator 41F-S
41F-1Z-A1 CRUSS OB42 OB42	99 82 6.2 32.8	3.8 5 5 5 5 5 5 5 5 5 5 5 5 5	No requirement
41F-1Z-A2-1/2 PCB terminal, PCB mounting	34.8 6.8 16.4 16.4 16.4 16.4 16.4 16.4 16.4 16.4 16.4 16.4 16.4	A1-A2+ COIL COIL	*marker 41F-M

Notes: * If need accesscry, please order with type.

DIMENSION OF RELATED COMPONENT (AVAILABLE)


Unit: mm

Marker




Marker


41F-M1



Jumper

41F-J1(blue) 41F-J1R(red) 41F-J1B(black)





Separator

41F-S

92.7



Things to be noticed when selecting sockets:

- Please choose suitable relay socket according to the actual mounting environment, relay contact poles and terminal layout. If there is any query on selection, please contact Hongfa for the technical service.
- 2. As for related components, they should be selected separately. Please do give clear indication of the types of relay sockets and related components you choose while placing order.
- 3. The above is only an example of typical socket and related component type which is suitable to RS41F relay. If you have any special requirements, please contact us.
- 4. Main outline dimension, outline dimension >50mm, tolerance should be \pm 1mm; 20mm<outline dimension \leq 50mm, tolerance should be \pm 0.5mm; 5mm<outline dimension \leq 20mm, tolerance should be \pm 0.4mm; outline dimension \leq 50mm, tolerance should be \pm 0.3mm.
- 5. DIN rail mounting: recommend to use standard rail $35 \times 7.5 \times 1$ mm, $35 \times 15 \times 1$ mm.

41F-1Z-C2-1/2/3/4/5

41F-1Z-C4-1/2/3/4/5

- 1. Please use the quick-break fuse with rating of 15Amp. for short-circuit protection.
- It may cause failure, fire or malfunction, when the sockets is continuously applied the power to for a long term In case of exceeding the upper limit ambient temperature. So please ensure that the ambient temperature is within the upper limit when using sockets.

Operating temperature upper limit: 55°C: 41F-1Z-C2-3/4

41F-1Z-C4-3/4

Operating temperature upper limit: 70°C: 41F-1Z-C2-1/2/5

41F-1Z-C4-1/2/5

- 3. Things to be noticed when selecting soft wiring.
- 1) 41F-1Z-C2-1/2/3/4/5

The soft wiring can be divided into the following types.

- Twisted line or single wire below 2.5mm² or below AGW14.
- · Within 2 roots when the twisted below 1.5mm² or below AGW16.

Be sure to use this size that the front end of the wire needs to be stripped of the 7mm~8mm insulation protection layer. (Figure 1)




Figure 1

·Use the recommended screwdriver specifications when wiring.

Plus driver: Shaft Diameter - 3.5mm.

Single driver: Figure 2.

Recommended tightening torque: 0.5N·m





Figure 2.

b) 41F-1Z-C4-1/2/3/4/5

The soft wiring can be divided into the following types.

Twisted line or single wire greater than 0.5mm² or less than 2.5mm² or greater than AWG 20 and less than AWG14. Be sure to use this size that the front end of the wire needs to be stripped of the 7mm² mm insulation protection layer. Use the recommended screwdriver specifications when wiring.



The insertion position of the wire and the screwdriver and the insertion direction of the screwdriver are as shown in Figure 4.





Figure 4

Please use cold pressed terminals when selecting twisted line.

The method of Wiring as shown in figure 5.


- Step 1. Insert screwdriver into socket with screwdriver patchhole.
- Step 2. Push the screwdriver in until it touches the stop position inside the socket, and keep the screwdriver in this position.
- Step 3. Please keep the screwdriver in this position, and wires inserted into the terminal insertion hole bottom.
- Step 4. Pull out the screwdriver and the wiring is completed.



Do not insert the wire insulation.

41F-1Z-C10-1/2/3/4/5

- 1. Please use the quick-break fuse with rating of 15Amp. for short-circuit protection.
- It may cause failure, fire or malfunction, when the sockets is continuously applied the power to for a long term In case of exceeding the upper limit ambient temperature. So please ensure that the ambient temperature is within the upper limit when using sockets.
 - Operating temperature upper limit* 55oC* 41F-1Z-C10-3/4
 - Operating temperature upper limit* 70oC* 41F-1Z-C10-1/2/5
- 3. Things to be noticed when selecting soft wiring.
 - The soft wiring can be divided into the following types.
 - Be sure to use this size that the front end of the wire needs to be stripped of the 8mm~10mm insulation protection layer.



* If the stripping protective layer is too short, it may cause the wire to be pulled out. If it is too long, it may have a short circuit with the adjacent wire. If the stranded wire of cold pressed terminal is used, please tighten the wire of stranded wire before use to avoid loose wire.

Use the recommended screwdriver specifications when wiring.*





Figure 2

* The insertion position of the wire and the screwdriver and the insertion direction of the screwdriver are as shown in Figure 3.



- Please use cold pressed terminals when selecting twisted line.
- The method of Wiring as shown in figure 4.
 Insert the wire into the wire insertion hole (circular hole) in the direction of (1) arrow, and insert the wire straight into the bottom, as shown in (2).






Figure 4

The method of Wiring as stitching in figure 5.
 Insert the wire into the wire insertion hole (circular hole) in the direction of (1) arrow, and insert the wire straight into the bottom, as shown in (2).




4. Mounting relay.


Presents the socket anti-stripping spring in an open state (see Figure 7), and aligns the relay to the main socket cavity (Figure 8). Then turn the buckle counterclockwise and press the relay gently until it is fully plugged into the socket (Figure 9).



5. Disassembly relay.

Disconnect the relay by pulling the anti lock buckle of the socket clockwise (please refer to the pictures attached for more details)





6. Installation socket. Insert the A of the socket into the rail and press it in the direction of the arrow.(Figure 11)




Figure 11

7. Disassembly socket.
Insert a screwdriver into B, turn in the direction of the arrow, lift the socket and remove the socket.(Figure 12)




Figure 11

Disclaimer

The specification is for reference only. See to "Terminology and Guidelines" for more information. Specifications subject to change without notice. We could not evaluate all the performance and all the parameters for every possible application. Thus the user should be in a right position to choose the suitable product for their own application. If there is any query, please contact Hongfa for the technical service. However, it is the user's responsibility to determine which product should be used only.